


Addendum



RX2 Receiver


ATTENTION: This model of the Danfoss Randall RX2 Two Zone Wireless Receiver has a NEW (9 pin) design of wallplate, and is not compatible with the older (6 pin) style of wallplate.

DIAGRAM 1 - RX2 Old Wallplate Wiring



Note: For mains voltage applications link terminals L and 2.

DIAGRAM 2 - RX2 New Wallplate Wiring



Please ensure that before fitting the RX2 receiver unit the new wallplate has been fixed correctly and the wiring adheres to that shown in diagram 2 above.

Danfoss can accept no responsibility for possible errors in catalogues, brochures, and other printed material. Danfoss reserves the right to alter its products without notice. This also applies to products already on order provided that such alterations can be made without subsequent changes being necessary in specifications already agreed. All trademarks in this material are property of the respective companies. Danfoss and the Danfoss logo are trademarks of Danfoss A/S. All rights reserved.



Danfoss Randall Ltd.

Ampthill Road
Bedford MK42 9ER
Tel: 0845 1217 400
Fax: 0845 1217 515
Email: danfossrandall@danfoss.com
Website: www.danfoss-randall.co.uk

